

# Download 2001 Ford F150 4 2l V6 Manual

Page 1 2001 F-150 Workshop Manual Page 1 of 12 SECTION 303-01B: Engine — 4.6L and 5.4L 2001 F-150 Workshop Manual IN-VEHICLE REPAIR Procedure revision date: 08/06/2003 Intake Manifold — 5.4L Removal WARNING: Do not smoke or carry lighted tobacco or open flame of any type when working on or near any fuel-related components. Highly flammable mixtures are always present and can be ignited. RockAuto ships auto parts and body parts from over 300 manufacturers to customers' doors worldwide, all at warehouse prices. Easy to use parts catalog. have a 2001 ford f-150 4.2l manual trans. it is leaking oil dripping between the oil pan and the tranny, valve cover and intake gasket have been replaced and it is still leaking.. about a quarter size or slightly larger every day... 2001 Ford F-150 Consumer Reviews View reviews for a specific F-150 model: ... (4.2L 6cyl 5M) Review. ... The engine and 5speed manual tranny sound like they are new still. The headlights are ...